

SOP / Safety Precaution

To ensure the safe storage and maintenance of lithium nickel manganese cobalt batteries during the summer season, preventing their temperature from exceeding 50° C




Never Hold Battery from Wire



Always Hold Battery from Base



Never placed battery loosely



Always place Battery in assigned slot




Avoid direct exposure to sunlight



Always place Battery in a shade




Never leave Battery Unattended while charging



Someone should attend battery while charging



Do not keep loose connection



Ensure tightly secured connection